
TECHNICAL CLARIFICATIONS

Date: 9 September 2025

Class: NEXEN Tyre E46 Class

Clarification #E46-T001

Bumper Brackets

Additional brackets may be fitted to provide extra support to the bumpers/bumper skins. Central OEM brackets must always be fitted.

This clarification allows only for **additional** reinforcement.

The additional brackets must be discrete and must serve no function outside of providing reinforcement.

Clarification #E46-T002

Brake Ducting / Undertray Panels - Rule 3.2 (f).

Rule 3.2 (f) was intended to allow the removal of the **front aggregate protective plate (example: 51718218384)** to provide more freedom for exhaust systems.

For the 2025-2026 season, Rule 3.2 (f) may also be applied to the other plastic undertrays / “splash guards” under the car.

These may be fitted or removed but must not be modified.

This includes the OEM plastic brake panels (example: 51718265467).

This clarification will be reviewed again for the 2026–2027 season.